2012 OND HSE & SD PLAN

2012 Key Business Activities

ИΕ	OBJECTIVES	Golden Rules	KBA	Driver	KPI	Target	Action Support		
	Visible & Felt Leader ship	Respect	OND CHAMPION: OND ONDLT site visit	ONS	100% completion	3 visits	OND		
	safety	Comply	Report IVMS Management analysis to ONDLT.	ONS	Quaterly Reports	4 reports	MSE/13 & ONS		
	Road s	Comply	Execute one Level II SP2000 compliance Audits.	СН	Q3	One audit report	ONS & MSE/13		
	Ø >		Engage RSST for Road Safety learnings	ONS	Quaterly Reports	4 reports	ONS & MSE/13		
	Impro	Intervene	Conduct 2 Driving Forums per area.	ONS	2 driver forums per area	Per schedule	MSE/13 & ONS		
İ			OND CHAMPION: ONQ						
		С	Report OND Actions Status to ONDLT.	ONS	Monthly Reports	12 reports	ONS Team		
		С	Report LSR Violations to ONDLT.	ONS	Monthly Reports	12 reports	ONS Team		
	Improve Worksite Hazard	I	Train supervisors on LSR peer-to-peer coaching.(MSE provides materials)	OND LT	% of supervisory staff trained	90% by end Q4	ONS		
	Management	I	Each contractor to conduct one hazard hunt per area per month in all worksites to improve hazard identification awareness.	OND LT	Monthly Reports	12 reports/area /contractor	ONS		
		С	Conduct level-2 PTW audit, one per area	ONO/ONE	4 audits	Q4	ONS		
		С	Report STOP performance quaterly to ONDLT	ONS	4 Reports	Q4	ONS		
			OND CHAMPION: ONE						
	Improve	Comply	Effective and Verified closure of all 2011 LOA findings.	СН	Quarterly Reports	100% by end Q4	MSE1		
	Contractor HSE Management	Comply	Map out peripheral activities and their HSE management.	СН	# of Contractors mapped	Q1-Q4	ONS/MSE1		
			OND CHAMPION: ONO						
		(.nmniv	Safety Critical Elements Asset register verification complete &	ONO	25% Quarterly	Q4	ONO/2		
	Improve	Comply	implemented In North (Corporate target) Number of interior ops staff to complete role related AI-PSM competence as defined by PR-1029 (Competence Assessment & Assurance) (Corporate target)	ONO	25% Quarterly	Q4	DTL		
	Process Safety	I AMNIV	Completion of Level 2 self assessments and cross-directorate audits (externally supported) Fahud & Yibal. (Corporate target)	ONO	25% Quarterly	Q4	ONO/2		
			Assessment of Red anomalies in Pacer/Cirras & corrective work orders established for those related to SCE. Deviations to be raised in FSR (As per PR-1983) (Corporate target)	ONO	25% Quarterly	Q4	ONO/6		
-			OND CHAMPION: ONP						
	NORM Management	I	Perform one NORM audit per area to comply with SP1170	OND LT	4 audits reports received	Q4	ONS & MCOH		
			OND CHAMPION: ONS						
		(.	CH to conduct one level - 2 audit to verify compliance of contractors with SP 1230/1231	СН	One audit report received	Q2	ONS & MCOH		
	Occupational Health	L.	Conduct Level-2 Radiation Safety Audits (one per area), covering NDT activities	ONO	100% compliance	Q1- Q4	ONS & MCOH		
			OND CHAMPION: ONF						
	Env	С	Complete the clean up of the oily waste pits	ONO	% cleaned pits	Q4	ONS & ONO/8		
•									

	1	2 LIFE SA	/ING RULI	ES	
Obtain a valid Permit to Work whenever required for the task at hand.	Verify isolation before work begins and use the specified life- protecting equipment.	Obtain authorization or a valid Permit to Work before overriding or disabling safety- critical equipment	Do not walk under a suspended	Follow the prescribed Safe Journey Management Plan.	While driving, do not use a mobile phone and do not exceed speed limits.
1 including the second	3	المقاف المعدات system override	7	9	11
2	4	6 2.0m	8	10	12
Conduct gas ests whenever required.	Obtain authorization or a valid Permit to Work before entering a confined space.	Use specified fall- prevention equipment when working at height.	Do not light up cigarettes, cigars or pipes in no-smoking areas.	Wear seat belts when in a moving vehicle.	Do not drive or work under the effect of drugs or alcohol.

	Below Ceiling	Ceiling	Above Ceiling	2011 Actual	Remarks			
LAGGING (Reactive) INDICATORS								
Work Related Fatalities	-	0	-	O				
LTIF	≥ 0.22	≤ 0.20	≤ 018	0.09 (0.23)	2012 LTIF = 2011 Ceiling LTIF - 10%			
RTAF	≥ 0.22	≤ 0.20	≤ 0.18	0.21 (0.10)	2012 RTAF = 2011 Ceiling RTAF - 10%			
	LEA	DING (Pro-	active) INI	DICATORS	3			
ONDLT Site Visits	2	3	4	3	OND LT quarterly visits			
Deliver OND HSE Plan	85%	95%	100%	94%	Quarterly Reviews			

2012 Level-1 Corporate Audit Plan

Area	Timing	Audit Type	MEASUREMENTS
All OND sites	18 th to 29 th Feb 2012	PTW COMPLIANCE	ONE AUDIT REPORT
All OND sites	2	HSE MS COMPLIANCE	ONE AUDIT REPORT
All OND sites	Q3	ISO 14001 RECERTIFICATION	ONE AUDIT REPORT

2012 Level 2 Audit Plan										
Area	Timing	Audit Type/ Area	Auditee	Leader	Team Members					
Lekhwair PAC	Apr 11	Compliance with HSE & SP 1232 requirements	ONO8	ONS(1)	ONO/1L MCOH/1 ONO8L A'Kader (Socat)					
All OND sites	Q1 - Q4	NORM: Compliance with SP1170	ONO/ONE	ONET2X	ONO1X ONO4X ONS/X					
All OND sites	Q1 - Q4	PTW Compliance	ONO/ONE	ONS(1)	ONO1X ONO16X ONE2TX ONS/X					
All OND sites	Q1 - Q4	Radiation Safety	ONO/ONE	DTL	ONO1X ONO4X ONET2X ONS/X					
All OND sites	Q1 - Q4	OH: Compliance with HSE & SP 1230& SP1231 requirements	ONO/ONE	DTL	ONO1X MCOH/1 ONE3X ONS/X					

AREA	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sept	Oct	Nov	Dec
FAHUD	OND-LT 22 Jan –25 Jan	ОМОЗ	ON05	ONE2Q	OND-LT 27May - 30 May	ONPF	ONE2L	ON06	OND-LT 02Sept- 05Sept	ONO2	ONE1	ONO
LEKHWAIR	OND-LT 22 Jan -25 Jan	ONO8	ONE2F	омоз	OND-LT 27May - 30 May	ONO5	ONE1	ONPL	OND-LT 02Sept- 05Sept	ONE2Q	ONO6	ONE
QA	OND-LT 22 Jan –25 Jan	ONE2L	ONE1	ON06	OND-LT 27May - 30 May	ONE2F	ONO2	ON05	OND-LT 02Sept- 05Sept	ONO8	ONPQ	ONO
YIBAL	OND-LT 22 Jan -25 Jan	ONO6	ONPY	ONO2	OND-LT 27May - 30 May	ONE2Q	ONE4	ONE2F	OND-LT 02Sept- 05Sept	ONO5	ONET	ONE2
Terminal on & off shore facilities		22 nd Feb										
Drilling South					14 th May							
RAH Phase-1											12 th Nov	

	A2: 2012	2 JOINT	MANA	GEME	NI HSE	INSPEC	HONS R	ELAIED	10 OND		
DATE	ACTIVITY AREA	HOST	MD	TD	UID	OSD	UPD	UWD	UEOD	GD	HD
19-02-12	FAHUD	ONO			X						
16-04-12	QARN ALAM	ONO	X								
10-09-12	FAHUD	ONE					X				
14-10-12	QARN ALAM	ONQO			X						
	QAS										
21-10-12	YIBAL	ONO	X								
06-11-12	LEKHWAIR			X							

